







木造倒壊ぶるる
補強金物の有無


名古屋大学 福和研究室
株式会社 日本システム設計




キリトリ線

キリトリ線

6




7




キリトリ線

8




9




キリトリ線


10




11



12




13




キリトリ線

14




15




キリトリ線

16



17



18




19



キリトリ線

20



21



キリトリ線


22



23



24



25



キリトリ線

26



27



キリトリ線

28



29



30



31



キリトリ線

32



33



キリトリ線

34



35



36



37



キリトリ線

38



39



キリトリ線

40



裏表紙